

ANAJET START UP SEQUENCE

			LONG START	SHORT START
1	MOTOR	J11-CN18	2	2
2	CARRIAGE	CN15		3
3	PUMP	CN17	4	4
4	MOTOR	J11-CN18	10	10
5	ENCODER	J4	12	12
6	CARRIAGE	CN15	15	15
7	ENCODER	J4	20	20
8	MOTOR	J11-CN18	24	SKIPS
9	CARRIAGE	CN15		SKIPS
10	PUMP	CN17	27	24
11	CARRIAGE	CN15	40	SKIPS
12	PUMP	CN17	42	SKIPS
13	CARRIAGE	CN15	48	SKIPS
14	PUMP	CN17		SKIPS
15	CARRIAGE	CN15	58	SKIPS
16	PUMP	CN17	60	SKIPS
17	CARRIAGE	CN15	72	SKIPS
18	MOTOR	J11-CN18	76	SKIPS
19	TABLE	J6-J14	82	30
	FINSIH		89	33